

SERVICE BULLETIN

00-1

Pivoting Second Tuck Assembly for 800 Series Machines



Available for models 804 and 806

Improved bag machine performance—even when converting lighter weight papers at high speeds.

- ◆ Improved bag quality—less chance of corner tear-out
- ◆ Tuck blade pivots with drum easily releasing from drum clamp at high speeds
- ◆ Minimizes the chance of bags pulling out of drum clamp
- ◆ Increased machine performance
- ◆ Increased tuck blade life

Contact the H.G. Weber Service Department at 920-894-2342.

H.G. WEBER & CO., INC.

725 Fremont Street, P.O. Box 196
Kiel, Wisconsin 53042-0196 U.S.A.

Service Phone: 920-894-2342
Service FAX: 920-894-4641

FLEXIBLE PACKAGING MACHINERY

E-mail: bagmachines@hgweber.com
Web Site: www.hgweber.com